

VZCZCXYZ0005
RR RUEHWEB

DE RUEHUL #0974 1340742
ZNR UUUUU ZZH
R 130742Z MAY 08
FM AMEMBASSY SEOUL
TO RUEHC/SECSTATE WASHDC 9901
INFO RUCPDOC/DEPT OF COMMERCE WASHDC 1800
RUEKJCS/SECDEF WASHINGTON DC
RUEPINS/HQ BICE INTEL WASHINGTON DC

UNCLAS SEOUL 000974

SIPDIS

STATE FOR PM/DTCC-BLUE LANTERN COORDINATOR

E.O. 12958: N/A
TAGS: AU ETTC KOMC KS
SUBJECT: FOLLOW-UP RESPONSE RE: BLUE LANTERN LEVEL 3 LICENSE
05-00005069

REF: A) State 00005069 B) SEOUL 00341

¶1. Per reftel, the ROK Air Force's (ROKAF) Logistics Command Inspector Bae Kang-ho confirmed receipt of the Attitude Director Indicator (ADI) parts referenced below for the F-4. The ADI parts were delivered to the ROKAF on April 8, ¶2008.

Quantity/Commodity

(1) 4 P/N:138947-01 NSN: 6610-00-0550-8543 Meter, Mechanism Rate of Turn Pointer
(2) 2 P/N:138990-01 NSN: 6610-00-0550-5399 Gearshaft, Helical-Spur
(3) 6 P/N:138950-01 NSN: 6610-00-074-9552 Meter, Mechanism, Horizontal
(4) 10 P/N:139002-01 NSN: 6610-00-014-3429 Indicator, Warning
(5) 4 P/N:11CT4E/B533 NSN:5990-00-578-8297 Synchro, Tranformer

¶2. Bluenier's (a DAPA registered supplier) Senior General Manager Park Sang-chun confirmed that 5 of the items listed in point (3) above, 6 of the items in point (4). and 4 of the items in point (5) were used to assemble the ADIs. The remaining parts have been stored in Bluenier's secure warehouse in the event that repairs to the ADIs are required. A photo of the Bluenier's warehouse will follow by e-mail.

Vershbow